



NOTICE TO MARINERS

(No. 15 of 2018)

Date: 19 September 2018

WICK HARBOUR and APPROACHES CHART 1462 REFERS

Mariners are advised that, with effect from 1400 hrs, 19 September 2018,

NORTH CARDINAL MARK - BUOY STATION (BREAK WATER (RU))

DUE TO WEATHER CONDITIONS THE TEMPORARY MARK BUOY IS OFF STATION

The base plate and rock are no longer visible at all states of tide
(only visible at low tide)

Mariners are advised to navigate with extreme caution

Location: **Latitude 58° 26'.28 North (WGS-84)
Longitude 003° 04'.33 West (WGS-84)**

Colour: **Black above Yellow**

Description of Structure: **Unlit North Cardinal Buoy**

Malcolm Bremner
Harbour Master

HARBOUR OFFICE
HARBOUR TERRACE
WICK. KW1 5HB

TEL: 01955 602030
FAX: 01955 605738

E MAIL: malcolm.bremner@wickharbour.co.uk

HARBOUR OFFICE
HARBOUR TERRACE
WICK. KW1 5HB

TEL: 01955 602030
FAX: 01955 605738
E MAIL: malcolm.bremner@wickharbour.co.uk