



www.wickharbour.co.uk

NOTICE TO MARINERS

(No. 10 of 2019)

DATE: 3rd November 2019

WICK HARBOUR

(CHART 1462 REFERS)

Latitude 58° 26' North Longitude 003° 04' West

Light outage on Port Lateral Mark (Wick Bay)

Due to storm conditions, the light on the Port lateral Mark in Wick Bay (Fl (2) R 6s, Latitude 58° 26.238' North (WGS-84 datum), Longitude 003° 04.100' West (WGS-84 datum) has suffered an outage and is out of action and will remain so until weather conditions allow access for investigation. The Buoy is still in position.

For further information Contact:

Malcolm Bremner: (Harbourmaster)

Ian Cormack: (Deputy Harbourmaster)

HARBOUR OFFICE
HARBOUR TERRACE
WICK.
KW1 5HB

TEL: 01955 602030 (24Hours)

FAX: 01955 605738

E MAIL: office@wickharbour.co.uk