



www.wickharbour.co.uk

NOTICE TO MARINERS

(No. 02 Of 2020)

DATE: 1st December 2020

WICK HARBOUR

(CHART 1462 REFERS)

Latitude 58° 26' North Longitude 003° 04' West

Port Lateral Mark (Wick Bay)

The light on the Port Lateral Mark situated in Wick Bay (Fl (2) R 6s), Latitude 58°26.238' North (WGS-84 datum), Longitude 003° 04.100' West (WGS-84 datum) is out of action. Swell conditions do not presently allow for repair work to be carried out. This will be done as soon as conditions allow.

Mariners are requested to navigate with care on approach to Wick Harbour during hours of darkness. Buoy remains in position unlit.

For further information Contact:

Malcolm Bremner: (Harbourmaster)

Ian Cormack: (Deputy Harbourmaster)

HARBOUR OFFICE
HARBOUR TERRACE
WICK.
KW1 5HB

TEL: 01955 602030 (24Hours)

FAX: 01955 605738

E MAIL: office@wickharbour.co.uk